





Parts list

 A x 4PCS		 B x 4PCS	
 C x 4PCS		D x 4PCS	
 E x 4PCS	 F x 4PCS	 G x 4PCS	 H x8PCS
 I x 1PC	 J x 1PC	 K x 1PC	 L x 4PCS
 M x 4PCS	 M6x15mm ① x 60PCS	 M6x40mm ②x 16PCS	 ③x 84PCS
 ④ x 8PCS	 ⑤ x 88 PCS	 ⑥ x 1PC	

STEP 1




STEP 2




STEP 3


Place R parts for the
4-sided support tubes
as shown in the diagram




STEP 4




STEP 5




STEP 6




STEP 7




STEP 8



STEP 9





STEP 10

